

Driver / Application Name	OS											
	Windows 95	Windows 98 Windows Me	Windows NT 4.0	Windows 2000	Windows XP (32 bit)	Windows XP (64 bit)	Windows Vista (32 bit)	Windows Vista (64 bit)	Windows 7 (32/64 bit)	Windows 8 (32/64 bit)	Windows 10 (32/64 bit)	Windows Server 2003/2008/2012/ 2016/2019 (32/64 bit)
Device Driver (STI driver)	NO	YES	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
Device Driver (WIA driver)	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
Multicolor Drop Out Utility	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES
IDR Engine Software	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
OCR Engine Software	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
Image Capture Plus	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
RTV	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO
Image Capture Software	NO	NO	NO	YES	YES	NO	YES	YES	YES	NO	NO	NO
Instant Scanning Software	NO	NO	NO	NO	YES	NO	YES	NO	NO	NO	NO	NO
User Utility	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES
Feed Speed Utility	NO	YES	YES	YES	YES	NO	YES	NO	NO	NO	NO	NO
Site Central Manager Suite	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
Export Import Tool	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
Panasonic Document Scanner	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1026C / KV-S1015C	NO	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES
KV-S1025C / KV-S1020C	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1045C	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1065C / KV-S1046C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1057C / KV-S1027C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S4085CW / KV-S4085CL / KV-S4065CW / KV-S4065CL	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S5055C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S5076H / KV-S5046H	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S7075C	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S2046C / KV-S2026C	NO	NO	NO	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S2048C / KV-S2028C	NO	NO	NO	YES	YES	NO	YES	YES	YES	YES	YES	NO
KV-S3085 / KV-S3105C	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S7065C	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S3065CW / KV-S3065CL	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S5905C	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S2045C / KV-S2025C	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S2055D / KV-S2055	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S2055W / KV-S2065L	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S2065W / KV-S2065L	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S1026C / KV-S1015C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1037X	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1025C / KV-S1020C	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1038 / KV-S1037 / KV-S1026C MK2	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1045C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1057C / KV-S1057C MK2 / KV-S1028Y / KV-S1027C MK2	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-N1058X / KV-N1058Y / KV-N1028X / KV-N1028Y	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1065C / KV-S1046C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S1057C / KV-S1027C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-SL1077 MK2 / KV-SL1066 MK2 / KV-SL1056 MK2 / KV-SL1055 MK2 / KV-SL1036 MK2 / KV-SL1035 MK2	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S2087	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S4085CW / KV-S4085CL / KV-S4065CW / KV-S4065CL	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S5055C	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S5076H / KV-S5046H	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S5100 / KV-S5096 / KV-S5095 / KV-S5086 / KV-S5085	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S7075C	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES	YES
KV-S7097 / KV-S7077	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S8150 / KV-S8147 / KV-S8130 / KV-S8127 / KV-S8120	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-SL3066 / KV-SL3056 / KV-SL3055 / KV-SL3036 / KV-SL3035	NO	NO	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES
KV-S2046C / KV-S2026C / KV-S2028C / KV-S2026C	NO	NO	NO	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S3085 / KV-S3105C	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S3065CW / KV-S3065CL	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S7065C	NO	YES	YES	YES	YES	NO	YES	YES	YES	NO	NO	NO
KV-S2055W / KV-S2055L	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S5905C	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S2045C / KV-S2025C	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S2065W / KV-S2065L	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S25D / KV-S25	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S555EX / KV-S550EX	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S6045W / KV-S6040W	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S6055W / KV-S6050W	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO
KV-S855D / KV-S855	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO	NO	NO

YES: Checked
NO: Not checked or Not work

Note

- * On Windows 2000/XP/Vista/7/8/10, Windows Server 2003/2008/2012/2016/2019, it is necessary to log on to "Administrator" privilege user to install the software bundled in Panasonic Document Scanners.
- * Do not use "Switch User" function of Windows Vista/7/8/10, Windows Server 2003/2008/2012/2016 while using the bundled software.
- * Windows 7/8/10 and Windows Server 2003/2008/2012/2016/2019 : USB interface is supported but SCSI interface is not supported.
- * ASPi drivers for your SCSI card are required when using the bundled software.
- * "Panasonic Document Scanner TWAIN Driver" includes TWAIN drivers for following models:
KV-S1025C, KV-S1026C MK2, KV-S1038/KV-S1037, KV-S1028Y, KV-S1027C MK2, KV-S1057C MK2/KV-S1027C MK2, KV-N1058X/KV-N1058Y/KV-N1028X/KV-N1028Y, KV-S1065C/KV-S1046C, KV-SL1066/KV-SL1056/KV-SL1055/KV-SL1036/KV-SL1035, KV-SL1077 MK2/KV-SL1066 MK2/KV-SL1056 MK2/KV-SL1055 MK2, KV-S2087, KV-S4085CW/KV-S4085CL/KV-S4065CW/KV-S4065CL, KV-S5055C, KV-S5076H/KV-S5046H, KV-S7075C, KV-S7097/KV-S7077, KV-S8150/KV-S8147/KV-S8130/KV-S8127/KV-S8120/KV-SL3066/KV-SL3056/KV-SL3055/KV-SL3036/KV-SL3035

Note for Windows Server 2003/2008/2012/2016/2019

- * The help page may be blocked for security.
- * Windows Server 2003 32bit: You can not save the image using the "Scanner and Camera" Wizard. Please use the WIA application (such as Paint), or use other interfaces (such as TWAIN).
- * When you scan with WIA, Windows Image Acquisition (WIA) service must be started.
- * Windows Server 2008/2012/2016/2019: You must install the "Desktop Experience".
- * If "Internet Explorer Enhanced Security Configuration (IE ESC)" is active, the help page may not be displayed correctly. To disable the IE ESC is as follows. (Example of Windows Server 2008)
 1. Open the Control Panel - Administrative Tools.
 2. Open the Server Manager.
 3. Click the Configure IE ESC.
 4. Select the off on both the user and Administrator.
 5. Click the [OK].
- * If the root certificate that is installed on the PC is older, the install may be fail. Please apply the latest Windows Update.


2. Models and Applications list

Model Name	Application Name													
	Device Driver (STI driver)	Device Driver (WIA driver)	Multicolor Drop Out Utility	IDR Engine Software	OCR Engine Software	Image Capture Plus	User Utility	Site Central Manager Suite	Export Import Tool	RTIV	Image Capture Software	Instant Scanning Software	Feed Speed Utility	PixView
KV-S1026C / KV-S1015C	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S1020C	YES	NO	YES	YES	YES	YES	YES	NO	NO	YES	YES	YES	NO	NO
KV-S1025C	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO
KV-S1038 / KV-S1037 / KV-S1026C MK2	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S1037X	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S1045C	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO
KV-S1065C / KV-S1046C	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S1057C / KV-S1027C	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S1058Y / KV-S1057C MK2 / KV-S1028Y / KV-S1027C MK2	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-N1058X / KV-A1058Y / KV-N1028X / KV-N1028Y	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-SL1077 MK2 / KV-SL1066 MK2 / KV-SL1056 MK2 / KV-SL1055 MK2 / KV-SL1036 MK2 / KV-SL1035 MK2	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-SL5100 / KV-SL5096 / KV-SL5095 / KV-SL5086 / KV-SL5085	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S2087	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S4085CW / KV-S4085CL / KV-S4065CW / KV-S4065CL	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO
KV-S5055C	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S5076H / KV-S5046H	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S7075C	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO
KV-S7097 / KV-S7077	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-S8150 / KV-S8147 / KV-S8130 / KV-S8127 / KV-S8120	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-SL3066 / KV-SL3056 / KV-SL3055 / KV-SL3036 / KV-SL3035	YES	YES	YES	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO	NO
KV-SS25D / KV-SS25	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES
KV-SS55EX / KV-SS50EX	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES
KV-S6043W / KV-S6040W	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	NO	NO	NO	NO
KV-S6055W / KV-S6050W	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	NO	NO	NO	YES
KV-SS855D / KV-SS855	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	NO	NO	NO	YES
KV-S2048C / KV-S2046C / KV-S2028C / KV-S2026C	YES	NO	NO	YES	YES	YES	YES	NO	NO	YES	YES	NO	NO	NO
KV-S2055W / KV-S2055L	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	NO	NO	NO	YES
KV-S7065C	YES	NO	YES	YES	YES	YES	YES	NO	NO	YES	YES	NO	NO	NO
KV-SS905C	NO	NO	YES	NO	NO	NO	NO	NO	NO	YES	YES	NO	NO	NO
KV-S2045C / KV-S2025C	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES	NO	NO	NO
KV-S2085W / KV-S2085L	NO	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES	NO	NO	NO
KV-S3085CW / KV-S3085CL	YES	NO	YES	YES	YES	YES	YES	NO	NO	YES	YES	NO	NO	NO
KV-S3085 / KV-S3105C	YES	NO	YES	YES	YES	YES	NO	NO	NO	YES	YES	NO	YES	NO

YES: Checked
NO: Not checked or Not work

Notice for 'ISIS' installer

KV-SS25D(U), KV-SS50 / 55EX(U), KV-S6040 / 6045W(U), V-S2055W(U), KV-S2055L(U), KV-SS855D(U)
When ISIS installer begin, the following message will appear. However, you can proceed to operate by pressing 'Continue' button.



Notice for 'PixView' software

The following screen will appear. However, there is no problem for operation.



* Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.