(c) Panasonic Corporation 2020-2022	
Version 1.13 -> 1.14	
	Improve the control of JAM.
Version 1.12 -> 1.13	
	Change in production line of factory.  This version does not include functional upgrade.
Version 1.11 -> 1.12	
	To deal with parts supply difficulties  This version does not include functional upgrade.
Version 1.10 -> 1.11	
	Improve the imprinter power control when the print area exceeds the paper.
Version 1.00 -> 1.10	
1.	Support USB 3.2 gen1.

/ KV-SL5095 MK2 / KV-SL5086 MK2 / KV-SL5085 MK2 \*\*\*

\*\*\* Release Note for Firmware of KV-S5058 / KV-SL5100 MK2 / KV-SL5096 MK2