

Scanner Driver for Mac (ICA)

If you install this scanner driver, you can scan with ICA compliant applications.

On how to scan, refer to the manual of each application.

<System requirements>

Model : KV-S1026C / KV-S1015C
 KV-S1057C / KV-S1027C
 KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035
 KV-S2087
 KV-S1058Y / KV-S1028Y / KV-S1057C MK2 / KV-S1027C MK2
 KV-S1037X
 KV-S1038 / KV-S1037 / KV-S1026C MK2
 KV-N1058X / KV-N1058Y / KV-N1028X / KV-N1028Y
 KV-SL3066 / KV-SL3056 / KV-SL3055 / KV-SL3036 / KV-SL3035
 KV-SL1077 MK2 / KV-SL1066 MK2 / KV-SL1056 MK2
 KV-SL1055 MK2 / KV-SL1036 MK2 / KV-SL1035 MK2

Interface : USB

<File>

Model	File name
KV-S1026C / KV-S1015C KV-S1057C / KV-S1027C KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035	<u>For Mac OS X 10.8 - 10.11, macOS 10.12 - 10.14</u> s1026_s1057_sl1066_ica12.pkg <u>For macOS 10.15 or later</u> PanaKVS_ICA_v3000.pkg
KV-S2087 KV-S1058Y / KV-S1028Y / KV-S1057C MK2 / KV-S1027C MK2 KV-S1037X KV-S1038 / KV-S1037 / KV-S1026C MK2 KV-N1058X / KV-N1058Y / KV-N1028X / KV-N1028Y KV-SL3066 / KV-SL3056 / KV-SL3055 / KV-SL3036 / KV-SL3035 KV-SL1077 MK2 / KV-SL1066 MK2 / KV-SL1056 MK2 KV-SL1055 MK2 / KV-SL1036 MK2 / KV-SL1035 MK2	<u>For Mac OS X 10.8 - 10.11, macOS 10.12 - 10.14</u> PanaKVS_ICA_v2101.pkg <u>For macOS 10.15 or later</u> PanaKVS_ICA_v3000.pkg

<Installing the scanner driver>

- 1) Double click the downloaded file.
- 2) Follow the on-screen instructions to complete the software installation.

<Uninstallation>

Delete the following files and the empty folders.

1) Launch the Finder .

2) Select the [Go]-[Go to Folder...] from menu.

3) Input the following folder path and click the [Go] button.

4) Select the following files and select the [File]-[Move to Trash] from menu.

Folder path : /Library/Image Capture/Devices

File :

Model	File name
KV-S1026C / KV-S1015C KV-S1057C / KV-S1027C KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035	Panasonic KVS Scanner.app or PanaKVS.app
KV-S2087 KV-S1058Y / KV-S1028Y / KV-S1057C MK2 / KV-S1027C MK2 KV-S1037X KV-S1038 / KV-S1037 / KV-S1026C MK2 KV-N1058X / KV-N1058Y / KV-N1028X / KV-N1028Y KV-SL3066 / KV-SL3056 / KV-SL3055 / KV-SL3036 / KV-SL3035 KV-SL1077 MK2 / KV-SL1066 MK2 / KV-SL1056 MK2 / KV-SL1055 MK2 / KV-SL1036 MK2 / KV-SL1035 MK2	PanaKVS.app

Folder path : /Library/Image Capture/Support/Panasonic/lib

File : libjpeg.62.dylib

libjpeg.dylib

<Information for scanning>

- If “An error occurred while communicating with the scanner” message appears, please check your application settings: “Scan Mode” = “Document Feeder”.

On how to set, refer to the manual of each application.

- If the power-saving mode (sleep) of the scanner is not released automatically when scanning from a computer, please release it by pressing the [Start / Stop] key.

- Mac, OS X and macOS are trademarks of Apple Inc., registered in the U.S. and other countries and regions.

- Portions of this software are based in part on the work of the Independent JPEG Group.